


PARK POSITION :

Because the wiper still has inertia the motor briefly becomes a generator. The output is now shorted causing the wiper to stop abruptly. 53b



Function	Polarity	Motor Code	Switch Code	Cable 12/24V
high speed	+	53b	H	red/grey
low speed	+	53	L	green/yellow
earth	-	31b		/black
common leg	-	53e	P	brown/bl-wh
self-parking	+	53a	B	black/white